



TO: C. F. Dunlap

RE: Inspection of Rad-Safe Station, Ujelang

GENERAL

Approximately 500 feet of D.B. cable should be brought in, as well as two Navy Cubes for ground water storage and fuel. Replace all furniture in all buildings. Replace all electric breakers and switch gear, and completely rebuild the pump house.

At 1545 the party departed Ujelang and arrived at Eniwetok at 1645.